



BRUHATH BENGALURU MAHANAGARA PALIKE
Office of the Asst.Executive Engineer(SWM), K.R.Pura Division,
Mahadevapura Zone, Bengaluru-560036


No:BBMP/AEE(SWM)/KRP-D/PR/80/2021-22.

Date:10/12/2021

CERTIFICATE

This is to certificate that **M/s AMAR JYOTHI PUBLIC SCHOOL**, Basavanapura Mian road, Devasandra. K.R.Pura Bangalore-36. Is inspected along with Junior Health Inspector, Ward no 53-Basavnapura BBMP on 09/12/2021 and it is to report as follows:-

1. The School Building Housing the class rooms are provided with proper ventilation and classrooms along with sufficient toilet facilities maintained in order and substantial repair conditions.
2. Sufficient toilets are provided in each floor of the building having water supply facilities.
3. The enter premises is kept in a near an hygienic condition.


Asst.Executive Engineer(SWM)
K.R.Pura Division, BBMP
BBMP, K.R Puram Division
Bangalore-36.